

Date

F5 Aiken 28 Dec 13 @ 10 45

MISCELLANEOUS FIELD NOTES

F5 Aiken SWL, AS, AQ, AH

Here to rebuild control.

Right side of wall was destroyed by high flow event.

Wall of sand was eroded towards Gauge box.

Reconstructed using black tarp, rocks, + ~ 10 sand bags.

Needs Serial cable out of CR 10 box

Needs basket

X6 @ 1220 1) 3.45 2) 9.87 3) 166.2 4) 4.72 5) 13.6

N₂ gas @ 2000

I 6 0 6

Stage @ 1222 3.455 1.85 (TD)

No. _____ of _____ sheets