

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 1-5, 1998

MISCELLANEOUS FIELD NOTES

House Cr @ H2

RDL

1645

Overcast
light breeze

control) Flume is still in rough shape
100% of water is leaking under the sand
bags & to the left of wall. Ice mound
under rock debris has melted causing
slumping of wall & waterproof material

I.W

OUT

1650

1.019

1.00 (Dry)

2.2 * *

-0.1 WT

-11.6 *

74.8 SC

PH = 8.37

* Probes not in water. Probes are dry
cannot reach flow at this point.

stream chem samples taken @ 1650

$Q_{est} = 0.10$