

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

WATER RESOURCES DIVISION

Date 12/16, 1995

MISCELLANEOUS FIELD NOTES

Lost seal stream @ F3

Installed staff plate @ 1640
@ 1640

	CR10	Field
stage	1.66	1.68
WT	8.3	7.5
SC	0.04	71

Bad SC reading on CR10.

Inspected CR10 program, found
a problem with storage locations.
Still bad readings.

Switched probes from 2050 to
2120 with no success. Probe is good.
Wiring OK. Has to be CR10 program.

87 Fixed CR10 program @ 2220

SC:	CR10	Field
	65.0	68.0