

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date Nov 26, 2001, 1901

MISCELLANEOUS FIELD NOTES

AIKEN CREEK @ F5

CJ, LT

• No Flow

- Came back to fix N₂

- replaced regulator, leaked

- replaced tank & put back original regulator

- No leaks

- But, no bubbles through the conoflow either....

* But NOW, bubbles like crazy!!

- bubble rate @ 10/80 sec ✓✓