

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 12/19, 1995

MISCELLANEOUS FIELD NOTES

Anderson creek @ H1

@ 2020	CR10	field
Stage	1.28	1.18
WT	0.7	-0.1
SC	23.3	39.3
PH		7.7

orifice is free

cleaned SC probe @ 2026
new SC CR10 = 46.2

Purged line @ 2031

new CR10 stage = 1.28

Perhaps the sutron transducer
has drifted?

Removed orifice line.

new CR10 = 1.10.

It appears problem is drift of
sutron, will leave as is, and
check that higher stage
maintain same datum correction
of -0.10'.