

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 11-29-03, 19

MISCELLANEOUS FIELD NOTES

CANADA STREAM @ FI S

• No Flow

• Here to address poor battery connection

- upon arrival, merely moving battery caused
positive wire to disconnect from battery

- Installed immediately new spade connector.

#6 @ 1446 @ Date & Time correct

stage 14.3

WT -14.3

SC 78.9

volts 14.4