

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 12/11, 1994

MISCELLANEOUS FIELD NOTES

Green Creek @ F9

visited site @ 1500. No flow yet this season. Flow appears imminent. Shorted battery fixed PS 2 wire. Ruined sm, blew the CI port on CR10. Will return to bring up exis, not logging data at this time.

1915 CR10 brought on-line with uploaded program all probes functioning and logging data

1926 first flow reaches control structure

Flow is leaking through hole at rebar. estimate $Q = 0.01$ cfs