

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 12-19-03, 19

MISCELLANEOUS FIELD NOTES

HAZEY CREEK @ FZ 9

- Just Flaming, has to be snow melt!
- Here to try fix of stage reading, find pipe!

AB@ 1925	OL
stage 1.02	ICE
AT -99999	"
WT "	"
V 13.9	

- Replaced Conaflex line to T-ducer, Nothing!

AB@ 1947
stage 1.02

- Closing Conaflex Outlet has no effect on stage, but Conaflex does cease to bubble, as does orifice

• Reducer does pressurize, just nothing to show for it.

• Can't find reason why N_2 down 50 PSI from yesterday.

- Slowed Bubble rate, N_2 @ 1360 PSI