

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 23 Nov 1979, 327 julian

MISCELLANEOUS FIELD NOTES

SVC, JCK, DLL

F3 Lost Seal @ 1156

Flow!

changed N_2 regulator from 2 psi \rightarrow 10 psi @ 60 bpm ^{34 bpm} JCK

Keypad reads all 88888 Unresponsive

WT = -2.1C S_2C -error, EC = 101.4 @ 1.8%

Unlogged + relogged power, no change.

Batt Voltage: 12.5 Array is charging
(6 not in direct light)

Getting out CPU, will check for program,
& reseed from CPU to SM.

back? stage

backi = 0.088 @ 12:22

backi = 0.085 @ 12:46

unable to communicate w/ CR10. left @ 12:50 ^{JCK}
using JCK laptop & both level logger & PC200
(check laptop w/ other CR10's)

OG: 0.05 @ 12:55

butlerate:

r H: 7.54

No. 1 of 1 sheets