

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 11/30/08, 19

MISCELLANEOUS FIELD NOTES

Qyx @ Lower Wright

- partly cloudy, wind from E

- NO FLOW

- 1015 Replaced N₂ tank, purged line
successfully

Replaced SM - checked settings
+ tested - got E 09 message

Tried switching dataloggers -
same message. Think we
need to replace SC line.
The one we brought is a
bit different than the attached
one - attempt to switch, fail.
Re-wired old SC line
(get same error) and left.

Will return next week (?) with
proper connection info.

No. of sheets
REW, LFS, ESS