

Date 27. Nov 13, @ 1113

MISCELLANEOUS FIELD NOTES

F7 Harnish ASS AM, SW

No flow, regulator was not bubbling, turned to 10 ps.

Here to switch boxes!

taking everything apart.

Cut orifice line w/ drill. trying to get out of old box.
Could not find new compression fitting, but will look
harder next time. Lots of snow & hopefully no flow
soon so can come back later to work on.

X6 @ 1325 1) 5.25 2) 16.7 3) 22.9 4) 2.7 5) 13.7

changed time again from 1230 to 1309

No. _____ of _____ sheets