

Date 27 Nov 13 @ 1100

MISCELLANEOUS FIELD NOTES

F5 Aiken ASS, AM, SWC

Here to replace box... ugh
No flow, moral low, bumper bars neglected

N₂ very low, cant find leak, replaced teflon.
500 psi.

time + date still ok!

*#6 1) 3.11 2) -10.6 3) -13.2 4) 2.9 5) 14.0

Needs broom + trash bag

No. _____ of _____ sheets