

Done

U. S. DEPARTMENT OF THE INTERIOR  
Geological Survey

Form 9-275-D  
(Jan. 1988)

WATER RESOURCES DIVISION

Date Nov 1, 1995

MISCELLANEOUS FIELD NOTES

(HI)

J. D. + J. S.

- Gagebox in good condition; very little snow inside
- Battery voltage old battery: 11.97 V
- Channel: no snow inside but downstream and upstream
- Datalogger: 2 minutes too slow
- D/L
- Install new battery
- no flow
- TOO MUCH SNOW TO REINFORCE DAM WALL