

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 1-7, 1998

MISCELLANEOUS FIELD NOTES

Crescent Str @ F8

1502

1745

Control is fine. Probes are in good position. orifice clear

stream chem @ 1745

$Q_{est} = 0.05$

<u>IN</u>	<u>OUT</u>	
-9999	2,88	4,239
8,6	*	1,36
236	136	2,879

sc Probe may be screwed as well.

* Temp Prob is broken.

Tried to fix -9999 in * 6 stage again.

still no luck.

C1 on CR10 is good, so is C2.

rewiring to C2 doesn't help.