

U. S. DEPARTMENT OF THE INTERIOR  
Geological Survey

Form 9-275-D  
(Jan. 1988)

WATER RESOURCES DIVISION

Date 11/25, 1998 1310

MISCELLANEOUS FIELD NOTES

Crescent Stream at F8 MNG, AB

Replaced N<sub>2</sub> Cylinder

Changed ~~to~~ program to look for transducer input from port C2 instead of C1. Changed lead on CR10 to port C2. This solved problem of -9999 readings in #6 for stage (record #1)

Batteries OK, No flow, cold ~ -10 C  
Sunny