

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date Nov 24, 192004 1700

MISCELLANEOUS FIELD NOTES

Huey Creek, site F2

- Huey is flowing, ≈ 0.001 CFS, likely snowmelt.
- Control structure and stream are under complete ice cover. Flume control was cleared of bridged ice. There is still ice anchored to bottom of flume.
- Gage box was swept out.
- * • No nitrogen in tank, one needs to be brought over and installed.
- * • No storage module in Gage. Need to bring a storage module over.
- Stream too shallow to get a water-quality sample.