

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 11-25-06, 19

MISCELLANEOUS FIELD NOTES

Lost Seal Creek F3

1745 - N₂ tank still 700 psi - left in,
dropped off fuel
- purged line - clear
- pulled old SM
- installed new SM - check is
OKay

- flume mostly clear - removed all
snow/ice left
- channel is clear & ready for
flow

*6	1	1.34	Stage
	2	3.27	AT
	3	-53.57	WT?
	4	14.0	BV
	86	2096.5	SC?

RW/ESS

(over →)

S 77 35.722

E 163 14.695

Alt - 666 ft

U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

- entire channel is wet, with
some intermittent flow. < 1.01

- @ flame staff reads < 0.01 ft.
However, no flow on orifice
side of flame.

- Q is just barely a trickle.
Too low to measure.