

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 11/28/10, 19

MISCELLANEOUS FIELD NOTES

Lost Seal @ F3

Flowing.

Keypad displays: 0888:8.8:8.H
unresponsive @ 1400.

Other keypad displays all 8's.

F 04.

* 0

E23 102

Time 1537, 2010, 332 pH: 7.53

WT: 2.1°C, SC: 260 μ S/cm ^{lab.} pH =

Checked program, gives error E23 102. Tried to move program to S11. got same error
but program was loaded successfully. Tried to fix program (delete lines 4000 etc).

Changed program (removed 1st bad command 'P0')

* 0. Works! Set correct time & loaded

program to sm.

more on back.

@ 1437 Back = 0.04' * 6 @ 1506 1) 29.49 slg
06 = 0.04' 2) -0.98 AT 3) -4.1 WT 4) 12.7 BV

No. _____ of _____ sheets

88) -2867 SC wrong!!! replace

U.S. DEPARTMENT OF THE INTERIOR
Geological Survey
WATER RESOURCES DIVISION
MISCELLANEOUS FIELD NOTES

Spencer looking for orifice, but can't find it!

Tank @ 1800 psi, line @ 12 psi.

Bubble rate...

orifice must be frozen, as bubbles
are not continuing long after
adjustment

Still can't find orifice, but it's
likely frozen in.

Gas components are all, so we
may come back + replace!

Re-tests.