9-276
(Rev. 7-67)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

Station Number ----------

LEVEL NOTES

Stream Simmons Creek

Locality Site H1

Party HH-SB Date 1/15, 1994

STATION	B. S.	HT. INST.	F. S.	ELEVATION	REMARKS
RM1				9.568	Bolt on US, Boulder-225' from well
	0.450	10.018			
RP1		(SS)	8.186	1.832	
Flume		(SS)	9.012	1.006	US - Bottom
Flume		(SS)	6.510	3.508	US - Top
Flume		(SS)	6.500	3.518	DS - Top
RM1			0.450	9.568	close (0.000)

No. ____ of ____ sheets Comp. by ____ Chk. by ____

U.S. GOVERNMENT PRINTING OFFICE: 1971-720-060