

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey
WATER RESOURCES DIVISION

Form 9-276
(July 1957)

STATION NUMBER

LEVEL NOTES

STREAM Andersen Crk
LOCALITY _____
PARTY ESG & LFS DATE 1/20/07, 19

STATION	B. S.	HT. INST.	F. S.	ELEVATION	REMARKS
(x) RM1	3.621	13.189		9.568	given ✓
RM2			9.692	3.497	1.830? 3.43? ✓
RM3			8.115	5.074	✓
USRS			9.619	3.570	flume corner ✓
DSRS			9.627	3.562	flume corner ✓
staff			9.609	3.580	-
PZ#1			12.120	1.069	bottom of flume, upsl.
orifice			12.039	1.150	temp orifice - not great ✓
PZF2			11.414	1.775	low pt in over-weir ^{hold spot}
TP1	7.186	11.719	8.656	4.533	
PZF2			9.943	1.776	
orifice			10.573	1.146	✓
PZF1			10.644	1.075	
staff			8.133	3.586	- 2.1143
DSLRS			8.155	3.564	4.511
USRS			8.145	3.574	✓
RM3			6.644	5.075	✓
RM2			8.219	3.500	2.541
(x) RM1			2.148	9.571	✓ 2.633
			CD =	0.003	✓

NO. _____ OF _____ SHEETS _____ COMP. BY _____ CHK. BY _____