

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey
WATER RESOURCES DIVISION

Form 9-276
(July 1967)

STATION NUMBER _____

LEVEL NOTES

STREAM Anderson
LOCALITY H1
PARTY JJ, CF, PW DATE 12-04-04, 19

STATION	B. S.	HT. INST.	F. S.	ELEVATION	REMARKS
RM1	0.233	9.801		9.568	bolt 225' US on right
RM2			6.303	3.498	bolt in rock in stream
RM3		behind hill	!		bolt downstream
USB			8.721	1.080	
USL			6.232	3.569	
DSR			6.232	3.569	
staff			6.227	3.574	top of staff plate @
orifice			8.700	1.101	2.5'
PZF			8.012	1.789	overflow
TP			2.800	7.001	
	3.220	10.221			
PZF			8.443	1.778	
orifice			9.133	1.088	
RM2			6.731	3.490	
RM1			0.64	9.581	$C = 0.013$