9-276
(Rev. 7-67)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

Station Number

LEVEL NOTES

Stream Simmons Creek

Locality H1

Party HH-PD Date 12/21, 1983

STATION	B. S.	HT. INST.	F. S.	ELEVATION	REMARKS
RM1				9.568	Bolt on Boulder 225' from wall
	0.743	10.311			
RP1		(SS)	8.462	1.849	
Flume		(SS)	9.300	1.011	Bot-US side
Flume		(SS)	6.800	3.511	Top-US side
Flume		(SS)	6.770	3.541	Top-D.S. side
RM1			0.742	9.569	close (+0.001)

No. ____ of ____ sheets ____ Comp. by ____ Chk. by ____

U.S. GOVERNMENT PRINTING OFFICE: 1971-720-060