

Form 9-276
(July 1957)

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey
WATER RESOURCES DIVISION

STATION NUMBER

LEVEL NOTES

STREAM Anderson Creek @ 411
LOCALITY _____
PARTY clj, jdc DATE 01-27-1961, 19__

STATION	B. S.	HT. INST.	F. S.	ELEVATION	REMARKS
(X) RM1	1.240	10.808		9.568	225' W right
RM2			7.301	3.507	bolt W of Flume
RM3			5.705	5.103	bolt, DS of control
top of staff			7.204	3.604	"2.50"
orifice			9.675	1.133	
PZF			9.709	1.099	
USL			7.205	3.603	
DSR			7.221	3.587	
PZF over flow			9.005	1.803	
TP			8.835	1.973	
TP	9.029	11.002		1.973	
PZF under flow			9.202	1.800	-0.003
DSR			7.430	3.572	-0.015
USL			7.402	3.600	-0.003
PZF			9.910	1.092	-0.007
orifice			9.870	1.132	-0.001
top of staff			7.404	3.598	-0.006
RM2			7.499	3.503	-0.004
RM3			5.905	5.097	-0.006
RM1			1.430	9.572	+0.004