

Done

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-276-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date Nov 3, 1995

MISCELLANEOUS FIELD NOTES

(FV)
J.V.

- Gagebox in good condition; only little snow inside
- Channel: completely packed with snow; cleaning of channel
- 2 Batteries in parallel
- not enough power for downloading
- no flow