

9-276
(Rev. 7-67)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

Station Number

LEVEL NOTES

Stream Commonwealth Stream
 Locality USGS Gage
 Party PUB-ARH Date 11/4, 1993

STATION	B. S.	HT. INST.	F. S.	ELEVATION	REMARKS
RM1				10.00	EST Anchor Bolt
	2.855				on top of large
		12.855			Rock on Right Bank,
					about 30° DS of
					Weir - Top of Bolt
(m)					
RP2		(SS)	3.569	9.286	EST ANCHOR BOLT
					on US face of
					Sandstone Boulder,
					11 feet US. of
					RP1 - Top of Bolt
RP1		(SS)	2.800	10.055	EST. 3/4" Rebar
					at U.S. Face of weir,
					on left side of
					channel, Top of
					U.S. edge of
					Rebar.
Orifice NUT		(SS)	4.425	8.430	TOP OF NUT
					ON ORIFICE
PZF		(SS)	4.330	8.525	Vinyl on low
					point of control
TP1			5.005	7.850	
	5.032	2.882			
Rm1			2.880	10.002	close (+0.002)
ORIFICE		(8.430-0.015)		8.415	Center (-0.015)

No. _____ of _____ sheets Comp. by _____ Chk. by _____