9-276
(Rev. 7-67)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

Station Number ----------

LEVEL NOTES

Stream Crescent Stream

Locality F8, station #6

Party HRH, PBV Date 11/25, 1993

STATION	B. S.	HT. INST.	F. S.	ELEVATION	REMARKS
RP1				4.239	Top of rebar at orifice - assume elev.
	4.515	8.754			equals 4.239
Top of orifice nut		(55)	6.146	2.608	
center of orifice	= 2.608 - 0.015 =			2.593	
RM2		(55)	3.787	4.967	Painted spot on rock 5' from orifice, D.S.
					on Right bank
RM4			4.199	4.555	Top of anchor bolt on same Rock as
					RM2
RM1			3.640	5.114	Painted spot on split rock 55' from orifice
					on Left bank, D.S.
RM3			3.213	5.541	Anchor bolt on same Rock as RM1
RP1			4.515	4.239	close = (0.000)

No ____ of ____ sheets Comp. by ____ Chk. by ____

U.S. GOVERNMENT PRINTING OFFICE: 1971-720-060