

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
WATER RESOURCES DIVISIONStation Number  
.....

## LEVEL NOTES

Stream Delta Stream  
Locality F10, Station #7  
Party HRH, PBV Date 11/26, 1993

| STATION                | B. S.         | HT. INST. | F. S. | ELEVATION | REMARKS                                                                                           |
|------------------------|---------------|-----------|-------|-----------|---------------------------------------------------------------------------------------------------|
| RPI                    |               |           |       | 6.900     | Top of Rebar - assumed 6.900'                                                                     |
|                        | 4.344         | 11.244    |       |           | old rebar, not cut                                                                                |
| Orifice<br>NAT         |               | (SS)      | 7.278 | 3.966     |                                                                                                   |
| center of<br>orifice = | 3.966 - 0.015 | =         |       | 3.951     |                                                                                                   |
| Rm?                    |               | (SS)      | 6.202 | 5.042     | Painted mark on rock<br>3' D.S. and left of<br>orifice                                            |
| Rm?                    |               | (SS)      | 5.650 | 5.594     | Painted mark on gray<br>rock 9' D.S. and 12' N<br>Right of orifice                                |
| Rm3                    |               | (SS)      | 5.626 | 5.618     | Top of Bolt in large<br>gray rock 8' right of<br>orifice, 1' U.S.                                 |
| Rm4                    |               | (SS)      | 0.375 | 10.869    | Top of Bolt in large<br>gray boulder, 100' U.S.<br>of orifice, on Right<br>Bank, 20' from channel |
| RPI                    |               | (SS)      | 4.343 | 6.901     |                                                                                                   |
| RP2                    |               | (SS)      | 5.718 | 5.526     | Top of Rebar at<br>orifice. Same rebar<br>as RPI, but after being<br>cut down.                    |
| Rm3                    |               |           | 5.624 | 5.620     |                                                                                                   |
|                        |               |           |       |           |                                                                                                   |
|                        |               |           |       |           |                                                                                                   |
|                        |               |           |       |           |                                                                                                   |
|                        |               |           |       |           |                                                                                                   |
|                        |               |           |       |           |                                                                                                   |

No. \_\_\_\_\_ of \_\_\_\_\_ sheets Comp. by \_\_\_\_\_ Chk. by \_\_\_\_\_