

9-276  
(Rev. 7-67)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
WATER RESOURCES DIVISION

Station Number

LEVEL NOTES

Stream Green Creek Page 1 of 2  
Locality Station F9, station #8  
Party HRH-PBV Date 11/27, 1993

STATION	B. S.	HT. INST.	F. S.	ELEVATION	REMARKS
Rm1				10.000	Anchor Bolt in flat gray rock, 35' to the right of gage box assume 40.000
	3.308	13.308			
Rm2		SS	7.012	6.296	Anchor bolt in top of large boulder on R.S. of wall
RPI		SS	8.800	4.508	Top of rebar at orifice tube
Orifice MUT- <del>TOP</del> center of orifice =		SS	9.625	3.683	
				3.683 - 0.015 = 3.668	
	cross-section = same 1-1				
STA	T99		SS	elev	
LS plastic wall	0		7.53	5.78	
	2		7.73	5.58	
	6		7.88	5.43	
	8		8.21	5.10	
	12		8.32	4.99	
	14		8.82	4.49	
	18		8.90	4.41	
	22		9.31	4.00	
	22.5		9.61	3.70	
	23.5		9.64	3.67	
	24		9.61	3.70	

No. \_\_\_\_\_ of \_\_\_\_\_ sheets Comp. by \_\_\_\_\_ Chk. by \_\_\_\_\_

9-276  
(Rev. 7-67)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
WATER RESOURCES DIVISION

Station Number

LEVEL NOTES

Stream Green Creek Page 2 of 2  
Locality F9, Station #8  
Party HRH, PBV Date 11/27, 1993

STATION	B. S.	HT. INST.	F. S.	ELEVATION	REMARKS
STA	T99		SS	elev	
	25		9.49	3.82	
	26		9.10	4.21	
	30		9.00	4.31	
	32		9.08	4.23	
	36		8.80	4.51	
	37		8.91	4.40	
	40		8.76	4.55	
	42		8.47	4.84	
	46		8.67	4.64	
	48		8.40	4.91	
RS wall @ Rock	50		7.57	5.74	
Rm1			3.302	10.006	close (to.006)

No. \_\_\_\_\_ of \_\_\_\_\_ sheets Comp. by \_\_\_\_\_ Chk. by \_\_\_\_\_