9-276
(Rev. 7-67)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

Station Number ---------

LEVEL NOTES

Stream Harnish Creek

Locality F7

Party HH-AL Date 1/5, 19 96

STATION	B.S.	HT. INST.	F.S.	ELEVATION	REMARKS
RM1				10.00	Top of bolt in Rock, 50' d.s. of weir orifice
	1.70	11.70	(SS)		
RP1			4.56	7.14	Top of 1" Pipe
weir			6.19	5.51	PZF
orifice			6.24	5.46	Top of NUT
			(FS)		
RM1			1.70	10.00	

No ____ of ____ sheets ____ Comp. by ____ Chk. by ____

☆ GPO 1984 0-452-826