

U. S. DEPARTMENT OF THE INTERIOR  
Geological Survey

Form 9-275-D  
(Jan. 1988)

WATER RESOURCES DIVISION

Date 11/22/05, 19

MISCELLANEOUS FIELD NOTES

JCK, SLH Harnish @ F7

- Opened gas box mostly clean.
- No  $N_2$  in tank.
- established conn. w/ CR10, correct date, time off by ~ 30 min. set to local time.
- replaced old SM F7B, w/ new one, F7A.
- checked SM address, set to fill & stop.
- Batt power for SM OK
- Copied CR10 program to SM
- changed  $N_2$  tank, new P ~ 1800 psi
- regulator set to 16 psi.
- bubble rate ~ 34/min.
- \*6 @ 1503
- stage: 5.54
- batt: 13.6

NO FLOW

orifice clear of snow & ice,  
much snow around control.

