

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

Station Number

LEVEL NOTES

Stream Harnish Cr @ F2
 Locality _____
 Party KDL PC Date 11-30, 19 97

| STATION | B.S. | HT. INST. | F.S. | ELEVATION | REMARKS |
|-----------|-------|-----------|-------|-----------|-------------------------------|
| RM1 | 0.170 | 10.170 | | 10.00 | Bolt in flat rock 25' L.S. up |
| RP1 | | | 3.050 | 9.120 | Rebar in channel |
| orifice | | | 4.730 | 5.440 | NUT |
| Low Point | | | 4.741 | 5.429 | PZF |
| TP | 4.502 | 10.202 | 4.470 | 5.700 | |
| LOW pt. | | | 4.758 | 5.444 | PZF |
| orifice | | | 4.760 | 5.442 | |
| RP1 | | | 3.082 | 9.120 | |
| RM1 | | | 0.201 | 10.001 | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

No 1 of 1 sheets Comp. by KL Chk. by KDL

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 11-30, 19 92

MISCELLANEOUS FIELD NOTES

Harnish Cr. @ F7

KL

Site visits 1410

Control is Dry + Free of Ice
No Flow here yet

N₂ tank 1800 psi

Feed 9 psi

Added 1 Battery, soldered terminals

Reset CR10 time from 1436 → 1437

*6 1 5.54

2 -9999

3 000

4 13.59