

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 15 Nov. 2005

MISCELLANEOUS FIELD NOTES

SLH, JCK, CJ House Creek @ H2

- Opened Gauge
- little bit of snow in box
- running off of a CR10 WP
- need new pressure transducer + datalogger!
- all very old!
- O₂si in N₂ tank \Rightarrow leaving full tank
- batteries reading 13.1 V
- attached keypad, no luck establishing comm's w/ datalogger.
- tried 2nd keypad, still no luck
- need to get CR10x ASAP! \rightarrow maybe not collected data good, to T. reset day 11/16
- pulled storage module, leaving a new one here 11/16
- old pressure transducer may function, but should be replaced w/ Satron pressure transducer when convenient
- batteries from '95 + '91 (perhaps time to replace)

N. Flow

H2

11/15/5

• $\frac{3}{10}$ foot of ice in flow...
may be tilted.

• Much ice along dam... above &
below.