Form 9-275F
(Apr. 2001)

U.S. DEPARTMENT OF THE INTERIOR
U.S. Geological Survey
WATER RESOURCES DIVISION
DISCHARGE MEASUREMENT AND GAGE INSPECTION NOTES

Meas. No. _____

Comp. by _____

Checked by _____

Julian Day 340.2

Sta. No. _____

Sta. Name F2 - Huey

Date Dec 6 , 20 02 Party JG

Width _____ Area _____ Vel. _____ G.H. _____ Disch. _____

Method _____ No. secs. _____ G.H. change _____ in _____ hrs.

Method coef. _____ Horiz. angle coef. _____ Susp. _____ Tags checked _____

Meter Type _____ Meter No. _____ Meter _____ ft. above bottom of wt.

Rating used _____ Spin test before meas. _____ ; after _____

Meas. plots _____ % diff. from rating no. _____ Indicated shift _____

GAGE READINGS						
Time					Inside	Outside
???					0.906	
	Start	No Flow				
	Finish					
Weighted MGH						
GH correction						
Correct MGH						

Samples collected: water quality, sediment, biological, other _____

Measurements documented on separate sheets: water quality, aux./base gage, other _____

Rain gage serviced/calibrated ____

Weather: _____

Air Temp. _____ °C at _____

Water Temp. _____ °C at _____

Check bar/chain found _____

Changed to _____ at _____

Correct _____

Wading, cable, ice, boat, upstr., downstr., side bridge, _____ ft., mi. upstr., downstr. of gage.

Measurement rated excellent (2%), good (5%), fair (8%), poor (> 8%); based on following conditions: Flow: _____

Cross section: _____

Gage operating: _____ Record Removed _____

2 batteries = Battery voltage: 12.9, 13.2 Intake/Orifice cleaned/purged: _____

Bubble-gage pressure, psi: Tank 2000 , Line _____ ; Bubble-rate _____ /min.

Extreme-GH indicators: max _____ , min _____ .

CSG checked: _____ HWM height on stick _____ Ref. elev. _____ HWM elev. _____

HWM inside/outside: _____

Control: _____

Remarks: Coroflow may have problems

GH of zero flow = GH _____ - depth at control _____ = _____ ft., rated _____

Sheet No. _____ of _____ sheets

6 Dec 2002

F2 Camp Stream (Huey)

- (1) fully charged battery unused, not connected to anything
- Both Batteries well charged
  (connected to CRIDX) 12.9 & 13.2 V

- pressure on tank 2000 psi

  *6.8 → channel 1 = .986

- conoflow has ~~strong~~ ~~pulse~~ escape of air in
  ~~clear vial~~
  has lots of bubbles coming out of
  sight feed cup
  - looks like new conoflow, old conoflow ~~on~~ disconnected floor

- checked commands, ~~on~~ /settings storage module
  3 all o.k.