

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

WATER RESOURCES DIVISION

Sunny,
Calm
nice!

Date 29 Jan, 2001, 19

MISCELLANEOUS FIELD NOTES

LAWSON CREEK eB3

CJ, PC

- Flowing
- N₂ @ 1700 PSI
- *6e

(Gave closeout)

- Date + time good
- control looks ok

	inside	outside	
Stage	6.53	1.17	@ 1318
SL	-	7.1 ^A	not temperature compensated ^{sc}
WT'c	-	0.2	
Volts	13.5	-	

- Swapped storage mods
- ran levels
- collected stream chem
- Hum measurement

Hum = e

LEVEL NOTES

STREAM Lawson Creek

LOCALITY _____

PARTY PC, CJ DATE 1/29/01, 19__

STATION	B. S.	HT. INST.	F. S.	ELEVA-TION	REMARKS
RMI				10.00	
	3.405	13.405			
RPI			5.613	7.792	rebar
Control			7.185	6.220	Drifted out
Control			7.540	5.865	PZF
RMI			3.405	10.000	