

U. S. DEPARTMENT OF THE INTERIOR  
Geological Survey

Form 9-275-D  
(Jan. 1988)

WATER RESOURCES DIVISION

Date 11/6, 1996 310 JULIAN

MISCELLANEOUS FIELD NOTES

B3 LAKE BANBY

- BATT Voltage = 12.5 V ON ARRIVAL  
Time = ?
- Disconnected old SM AFTER UNPLUGGING  
BATT. Picked up w/ new BATTERY  
(SAME AS B2) AND INSTANT "7128".
- SM ADDR. = 1
- YES FILL & STOP
- SM BATT. OK
- Set time
- LOG 1
- Hooked up solar
- New NE tank No leaks