

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

Form 9-275-D
(Jan. 1988)

WATER RESOURCES DIVISION

Date 11/13, 1998 1530

MISCELLANEOUS FIELD NOTES

B³, Lawson Cr.

1 of 2
pics looking
pic.
AB, MG

- light is on

- swapped N_2 tank high = 1900psi
low = 10psi

- batteries are good.

- swapped SMs

- reset CR 10 Time

- NO FLOW here yet

- control looks good, no flume, rebar
tape down.