

Form 9-276  
(July 1957)

U. S. DEPARTMENT OF THE INTERIOR  
Geological Survey  
WATER RESOURCES DIVISION

STATION NUMBER

STREAM F3 Lost Seal @ 1430 LEVEL NOTES  
LOCALITY \_\_\_\_\_  
PARTY SWC CBR DATE 12 Jan 11, 1958

| STATION | B. S. | HT. INST. | F. S. | ELEVATION | REMARKS |
|---------|-------|-----------|-------|-----------|---------|
| x RM3   | 3.831 | 10,841    |       | 7.01      |         |
| RM4     |       |           | 3.722 | 7.119     |         |
| PZF     |       |           | 6.640 | 4.201     |         |
| Orifice |       |           | 6.610 | 4.231     |         |
| RP1     |       |           | 5.610 | 5.231     |         |
| Staff   |       |           | 4.655 | 6.186     |         |
| USL     |       |           | 4.610 | 6.231     |         |
| DSR     |       |           | 4.741 | 6.100     |         |
| TP1     |       |           | 5.697 | 5.144     |         |
| TP1     | 5.538 | 10,682    |       |           |         |
| DSR     |       |           | 4.579 | 6.103     |         |
| USL     |       |           | 4.446 | 6.236     |         |
| Staff   |       |           | 4.493 | 6.189     |         |
| RP1     |       |           | 5.451 | 5.231     |         |
| orifice |       |           | 6.450 | 4.232     |         |
| PZF     |       |           | 6.481 | 4.201     |         |
| RM4     |       |           | 3.563 | 7.119     | 0.0     |
| RM3     |       |           | 3.670 | 7.012     | + .002  |
|         |       |           |       |           |         |
|         |       |           |       |           |         |
|         |       |           |       |           |         |
|         |       |           |       |           |         |

NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS \_\_\_\_\_ COMP. BY \_\_\_\_\_ CHK. BY \_\_\_\_\_