9-276
(Rev. 7-67)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

Station Number ----------

LEVEL NOTES

Stream Lost Seal Stream
Locality F3, site 3 Page 1 of 2
Party HRH, PBV Date 11/24, 1993

STATION	B.S.	HT. INST.	F.S.	ELEVATION	REMARKS
RM1				7.000'	Chiseled mark on top of brown Boulder on R.S. of river, D.S. of wall. - assume = 7.00'
	2.420	9.420			
RP1		(SS)	4.015	5.405	Top of Rebar on left side, U.S. of weir
RM3		(SS)	2.412	7.008	est anchor bolt on top of same Rock as RM1
RM4		(SS)	2.290	7.130	est anchor bolt on top of brown rock, 3½' diameter on left bank about 10' D.S. of gage.
Top of "T" on muffler pipe		(SS)	5.480	3.940	
center of orifice	Dist from Top of "T" = 0.14'			3.800	elev = 3.940 - 0.140
	X Section - same HI				
STA	Tag		SS	elev	
CS-weir	1.0		3.42	6.00	@ Fence Post
	1.5		3.86	5.56	
	2.0		4.28	5.14	
	2.3		4.97	4.47	
	3.2		5.09	4.33	
	3.4		5.29	4.13	
	3.8		5.56	3.86	
	4.0		5.40	4.02	
	4.6		5.43	3.99	
	4.7		4.84	4.58	

No. ____ of ____ sheets ____ Comp. by ____ Chk. by ____

U.S. GOVERNMENT PRINTING OFFICE: 1971-720-060

9-276
(Rev. 7-67)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

Station Number ----------

LEVEL NOTES

Stream Lost Seal Stream
Locality F3 - station #3 Page 2 of 2
Party HRH - PBV Date 11/24, 1993

STATION	B.S.	HT. INST.	F.S.	ELEVATION	REMARKS
Stg	Tag		SS	elev	
	5.8		5.21	4.21	
	6.5		5.30	4.12	
	6.6		5.60	3.82	
	7.0		5.09	4.33	
	7.7		5.24	4.18	
	7.9		5.57	3.85	
	8.7		5.55	3.87	
	9.7		5.12	4.30	
	9.9		4.80	4.62	
	11.3		4.52	4.90	
	12.0		4.54	4.88	on s. bag.
	12.7		3.33	6.09	
RS weir	13.0		3.29	6.13	
RM1			2.420	7.00	close (0.000)

No. ____ of ____ sheets ____ Comp. by ____ Chk. by ____

U.S. GOVERNMENT PRINTING OFFICE: 1971-720-060