

U. S. DEPARTMENT OF THE INTERIOR
Geological Survey

WATER RESOURCES DIVISION

348

Date 12/14, 19 95

MISCELLANEOUS FIELD NOTES

Onyx River @ vandy weir

visited gage @ 1030.

Nut off orifice line, line not visible
appears to be functioning OK, anyway.

changed power chords @ 1044

shoveled sand on weir cracks from
1030 to 1100 to try to seal minor
leaks.

@ 1100

	CR 10	Field ^{0.686'} tape up
Stage	1.86'	0.209m) 0.81'
wt		2.2
sc		63.6
PH		

Installed solar panels @ 1115

first flow on Dec 3, @ 1445

Installed new program @ 1140

took discharge @ 1227

surveyed RP's and Lake level @ 1400

@ 1505 IG = 1.87'

Pulled orifice line through cap, but could not

@ 1520 IG = 1.86' attach nut