

U. S. DEPARTMENT OF THE INTERIOR  
Geological Survey

Form 9-275-D  
(Jan. 1988)

WATER RESOURCES DIVISION

J.U. + J.S.

Date Nov 7, 19 95 @ 21.30

MISCELLANEOUS FIELD NOTES

(B1)

- Reset datalogger / SM battery okay
- Reset time of datalogger → datalogger was 4.10 minutes too slow
- Replacement of nitrogen tank
- $N_2 = 1910$  psi for the new tank
- Placement of stones on the upstream side of the dam
- No flow