

U. S. DEPARTMENT OF THE INTERIOR  
Geological Survey

Form 9-275-D  
(Jan. 1988)

WATER RESOURCES DIVISION


Date 11-14, 1992

MISCELLANEOUS FIELD NOTES

Santa Fe Stream @ 82 KDL

- Gage looks good except  $N_2$  gage 1325  
 $N_2$  tank a bit low (500 psi) no leaks found  
may be Regulator gage reading wrong.

Ice in channel and on orifice  
Flume Crossbar is cracked + Buckled.



estimated  $Q = 0.02$  cfs  
all  $Q$  is below orifice

Ask Harry about breach in channel 10 meters  
to left of flume. Ice is worn.